



Rating form completed by: **MAFFEI STRUCTURAL ENGINEERING**
 maffei-structure.com
 Dom Campi, Noelle Yuen, Joe Maffei

Text in green is to be part of UC Santa Cruz building database and may be part of UCOP database

UC Santa Cruz building seismic ratings
Thimann Laboratory

CAAN #7116
 568 Steinhart Way, Santa Cruz, CA 95064
 UCSC Campus: **Main Campus**



DATE: 2018-12-30



Rating summary	Entry	Notes
UC Seismic Performance Level (rating)	VI (Very Poor)	Assumes no prior retrofit was made
Rating basis	Tier 1	ASCE 41-17 ¹
Date of rating basis	2018	
Recommended list assignment (UC Santa Cruz category for retrofit)	Priority A	Priority A=Retrofit ASAP Priority B=Retrofit at next permit application
Ballpark total construction cost to retrofit to IV rating ²	High (\$200-\$400/sf)	See recommendations on further evaluation and retrofit.
Is 2018-2019 rating required by UCOP?	Yes	We did not find a documented previous rating
Further evaluation recommended?	During retrofit design	To determine if a prior retrofit was made in 1989. If so, reassess.

¹ We translate this Tier 1 evaluation to a Seismic Performance Level rating using professional judgment. Non-compliant items in the Tier 1 evaluation do not automatically put a building into a particular rating category, but we evaluate such items along with the combination of building features and potential deficiencies, focused on the potential for collapse or serious damage to the gravity supporting structure that may threaten occupant safety. See Section III B of the UC Seismic Policy and Method B of Section 321 of the 2016 California Existing Building Code.

² Per Section 3.A.4.i of the Seismic Program Guidebook, the cost includes all construction cost necessitated by the seismic retrofit, including restoration of finishes and any triggered work on utilities or access bility. It does not include soft costs such as design fees or campus costs. The cost is in 2019 dollars.

Building information used in this evaluation

- Architectural drawings by Anshen & Allen, "Natural Sciences Unit One, University of California, Sant Cruz," 17 Jan 1964.
- Structural drawings by T.Y. Lin & Associates International, "Natural Sciences Unit One, University of California, Sant Cruz," 17 Jan 1964, sheets S1 through S17. Set contains drawings for shops building and lecture hall, which are separate structures not reviewed herein.
- Slab prestress tendon drawings by Western, "Natural Sciences Unit One, University of California, Sant Cruz," 6 sheets from various dates in 1964.
- University of California building database information provided by Jose Sanchez (UCSC) on 2018-11-20.

Additional building information known to exist

Building database indicates building was retrofit in 1991. A letter by Wildman & Morris to Campus, dated December 6, 1989, indicates that building is currently undergoing a seismic retrofit, as designed by ED2, Architects, and Wildman & Morris, Engineers. However, campus has located no drawings or other records for retrofit and campus facilities personnel have not observed retrofit measures.

Scope for completing this form

Reviewed structural drawings for original construction and carried out ASCE 41-17 Tier 1 evaluation. We made a brief site visit. We did not perform the Tier 1 nonstructural evaluation, but we looked for potentially hazardous nonstructural components during our site visit. No nonstructural hazards were identified.

Plans contain drawings for Thimann Lecture Hall and a shops building, both of which are separate structures from the Thimann Lab building. These separate structures were not part of this review.

It can be seen from satellite imagery that various penthouse and greenhouse structures have been added to roof of the Lab building. These have not been reviewed or assessed. It can also be seen that a bridge connecting to Sinsheimer has been constructed that appears to closely abut the building; we did not observe whether the bridge is connected to the building.

Brief description of structure

The Thimann Lab building was designed in 1964 by the architectural office of Anshen & Allen and the structural office of T.Y. Lin International. The building is 3 story structure that contains approximately 89,000 square feet according to campus records. The building is a rectangle in plan, measuring 238 feet long (east-west) by 100 feet wide (north-south). Each story is 13'-0" in height with an overall building height of 39 feet from the Ground Floor to the roof.

The building is of all concrete construction, with cast-in-place post-tensioned concrete floor and roof slabs, cast-in-place conventionally reinforced concrete columns and walls at the interior, and a façade constructed with precast concrete columns and wall panels.

Penthouses and greenhouses that are presumably of lightweight construction have been added to the roof since its original construction.

Foundation System: The site is moderately sloping. The superstructure is founded on shallow footings. Strip footings run around the building perimeter to support the perimeter columns and the wall elements (of various types) that infill the columns. There are isolated spread footings at interior columns. Strip footings are provided below the wall elements of concrete, precast concrete, and concrete block masonry (CMU) that exist at the first level.

Structural system for vertical (gravity) load: The floors and roof are each constructed using a 13-inch thick, two-way post-tensioned, lightweight concrete flat plate slab. The slab is supported by 2-foot square concrete columns at the interior; bay size is 40 feet in the east-west direction and 40'-20'-40' in the north-south direction. The slab is supported by precast concrete columns, spaced at 10 feet on center, around the perimeter.

Concrete walls that surround and support the stairs also serve as bearing walls for the floors.

Structural system for lateral forces

It is not clear what elements were intended in the design to act as the seismic lateral force resisting system. Elements that may play a role consist of the following:

- 8-inch thick, lightly reinforced (1 layer of #4@10" o.c.) cast-in-place concrete walls, located at the two stairs, can resist some lateral force, but are well below the necessary capacity to resist the seismic demands of the entire building.
- Precast concrete columns at the building façade, shaped for appearance and approximately 1.5 feet x 2 feet in plan, with #3 @ 14" o.c. transverse reinforcement. The precast concrete columns are continuous between floors and can resist some lateral force.
- 4"-thick vertically-prestressed lightweight concrete wall panels at the façade, framing between columns and doveled into floors but not connecting to columns except at floor lines. The panels have large window openings, and furthermore are not doveled into the building foundation, so they do not appear intended to act as shear walls. The panels are also not moment connected to the columns, so frame action does not occur between columns and panels, except possibly through coupling action between the third and second floors.

For this seismic evaluation, we assumed the following lateral force resisting system:

- Between the third floor and the roof, the precast wall panels are perforated with large window openings, and lateral forces are resisted by the precast columns plus the 8" concrete walls at the stairs.
- Between the second and third floors, the columns are perforated with vertical slots for tall window openings, and lateral forces are resisted by the precast wall panels plus the 8" concrete walls at the stairs.
- Between the first and second floors, because the wall panels are not shown in the drawings as doveled to the foundation, lateral forces are resisted only by the precast columns plus the 8" concrete walls at the stairs. Frame action from the wall panel above likely provides added stiffness to reduce drift.

Brief description of seismic deficiencies and expected seismic performance including mechanism of nonlinear response and structural behavior modes

The following deficiencies are based on review of original structural drawings for the building from 1964. A letter from 1989 indicates that retrofit work on the building was in progress at that time. However, UCSC has no record of retrofit drawings and is not aware of any additional visual observation of retrofitted items in the building. For the purposes of this rating, we assume that these deficiencies have not been addressed. If subsequent investigation by UCSC indicates that some or all of these deficiencies have been addressed by retrofitting, this rating should be updated to consider the benefits of the provided retrofitting. Also, during our site visit, we observed that the openings in the precast wall panels at the façade do not match the original structural drawings. For example, in locations where the drawings show the wall set back from the face of the building, the wall currently does not step back. Also, window openings are smaller than shown in the drawings.

Seismic deficiencies of the building include the following:

- The wall panels do not connect to the foundation.
- The precast columns between the roof and the third floor appear to be shear critical.
- The exterior precast columns and 8" cast-in-place walls are overstressed by a factor of 1.4 between the roof and the third floor, and a factor of 2.0 between the second and first floor, for seismic demands.
- The exterior precast wall panels are overstressed between the second and third floor by a factor of 3.0 for seismic demands, assuming Tier 1 $M_s = 2.0$ consistent with the M_s value used to evaluate the precast columns.
- The 8" cast-in-place walls are lightly reinforced, with the horizontal steel reinforcement ratio = 0.0016. The wall between the stair and the elevator core is inadequately connected to the floor diaphragm.
- We could not find details of the interior concrete columns other than a detail of the connection to the footing (J-S9). Based on this and other details, we expect that the columns are lightly tied and prone to shear failure.

The building's lack of a reliable lateral force resisting system makes it a potential collapse risk in a major earthquake.

Structural deficiency	Affects rating?	Structural deficiency	Affects rating?
Lateral system stress check (wall shear, column shear or flexure, or brace axial as applicable)	Y	Openings at shear walls (concrete or masonry)	Y
Load path	Y	Liquefaction	N
Adjacent buildings	N	Slope failure	N
Weak story	N	Surface fault rupture	N
Soft story	N	Masonry or concrete wall anchorage at flexible diaphragm	N
Geometry (vertical irregularities)	N	URM wall height-to-thickness ratio	N
Torsion	Y	URM parapets or cornices	N
Mass – vertical irregularity	N	URM chimney	N
Cripple walls	N	Heavy partitions braced by ceilings	N
Wood sills (bolting)	N	Appendages	N
Diaphragm continuity	N		

Summary of review of non-structural life-safety concerns, including at exit routes.³

In our brief site visit, we did not observe any non-structural life-safety concerns, but there are a number of areas of the building that we did not observe. When more detailed evaluations of the building are made, as we recommend, they should include a review of details of construction of glazed wall at entry lobby and condition of connections of steel tube stringers to landings at exterior exit stairs.

UCOP non-structural checklist item	Life safety hazard?	UCOP non-structural checklist item	Life safety hazard?
Heavy ceilings, feature or ornamentation above large lecture halls, auditoriums, lobbies or other areas where large numbers of people congregate	None observed	Unrestrained hazardous materials storage	None observed
Heavy masonry or stone veneer above exit ways and public access areas	PC panels	Masonry chimneys	None observed
Unbraced masonry parapets, cornices or other ornamentation above exit ways and public access areas	None observed	Unrestrained natural gas-fueled equipment such as water heaters, boilers, emergency generators, etc.	None observed

Discussion of rating

Because of the potential collapse risk, we rate the building as VI (Very Poor). The rating applies unless subsequent investigation indicates that the deficiencies described herein have been addressed by retrofit. We and UCSC have not yet found any documentation of retrofit.

Recommendations for further evaluation or retrofit

We recommend that the University retrofit this building as a high priority. One option for retrofitting would include new cast-in-place concrete walls that are sufficiently strong to resist the high lateral forces anticipated at this site and sufficiently stiff to protect the concrete frame and façade panel elements. Further evaluation and drawing search is needed to determine if any retrofit was constructed, and would be done to further define the scope of required retrofitting. Otherwise no further evaluation is needed to confirm the inadequacy of the seismic performance.

³ For these Tier 1 evaluations, we do not visit all spaces of the building; we rely on campus staff to report to us their understanding of the type and location of potential non-structural hazards.

Peer review of rating

This seismic evaluation was discussed in a peer review meeting on 24 July 2019. The reviewers present were Bret Lizundia of R+C and Jay Yin of Degenkolb. Comments from the reviewers have been incorporated into this report. The reviewer agreed with the assigned rating.

Additional building data	Entry	Notes
Latitude	36.998097	
Longitude	-122.061995	
Are there other structures besides this one under the same CAAN#	Not Known	There is a structurally separate Lecture Hall and Shops Building that are shown on drawings.
Number of stories above lowest perimeter grade	3	
Number of stories (basements) below lowest perimeter grade	0	Unoccupied Crawl Space is not considered a story
Building occupiable area (OGSF)	88989	
Risk Category per 2016 CBC Table 1604.5	II	Classroom occupancy
Estimated fundamental period	0.25 sec	Estimated using ASCE 41-17 equation 4-4 and 7-18
Building height, h_n	39 ft	Structural height defined per ASCE 7-16 Section 11.2
Coefficient for period, C_t	0.020	Estimated using ASCE 41-17 equation 4-4 and 7-18
Exponent on height, β	0.75	Estimated using ASCE 41-17 equation 4-4 and 7-18
Site data		
975 yr hazard parameters S_s, S_1	1.286, 0.488	
Site class	D	
Site class basis ⁴	Geotech	See footnote below
Site parameters F_a, F_v ⁵	1, 1.81	
Ground motion parameters S_{cs}, S_{c1}	1.286, 0.885	
S_a at building period	1.29	
Site V_{s30}	900 ft/s	
V_{s30} basis	Estimated	Estimated based on site classification of D.
Liquefaction potential	Low	
Liquefaction assessment basis	County map	See footnote below
Landslide potential	Low	

⁴ Determination of site class and assessment of geotechnical hazards are based on correspondence with Pacific Crest Geotechnical Engineers and Nolan, Zinn, and Associates Geologists. [Revised Geology and Geologic Hazards, Santa Cruz Campus, University of California, Job # 04003-SC 13 May 2005]. Site class is taken as D throughout the main campus of UC Santa Cruz. The following links provide hazard maps for liquefaction, landslide, and fault rupture:


<https://gis.santacruzcounty.us/mappallery/Emergency%20Management/Hazard%20Mitigation/LiquifactionMap2009.pdf>

<https://gis.santacruzcounty.us/mappallery/Emergency%20Management/Hazard%20Mitigation/LandslideMap2009.pdf>


<https://gis.santacruzcounty.us/mappallery/Emergency%20Management/Hazard%20Mitigation/FaultZoneMap2009.pdf>

⁵ F_v factor used does not include the requirements of Section 11.4.8-3 of ASCE 7-16 that are applicable to Site Class D, and which per Exception 2 would result in an effective F_v factor of 2.72 (1.5 times larger). At the Santa Cruz main campus this only affects structures with $T > 0.69$ seconds. We understand that the appropriateness of this requirement of Section 11.4.8 might be reviewed by UCOP.


Landslide assessment basis	County map	See footnote below
Active fault-rupture identified at site?	No	
Fault rupture assessment basis	County map	See footnote below
Site-specific ground motion study?	No	
Applicable code		
Applicable code or approx. date of original construction	Built: 1964 Code: 1964 UBC	Code inferred based on design year
Applicable code for partial retrofit	-	Possible retrofit in 1989
Applicable code for full retrofit	-	
FEMA P-154 data		
Model building type North-South	PC2 – Precast concrete frames (with shear walls)	
Model building type East-West	PC2 – Precast concrete frames (with shear walls)	
FEMA P-154 score	N/A	Not included here. Tier 1 evaluation.
Previous ratings		
Most recent rating	-	
Date of most recent rating	-	
2 nd most recent rating	-	
Date of 2 nd most recent rating	-	
3 rd most recent rating	-	
Date of 3 rd most recent rating	-	
Appendices		
ASCE 41 Tier 1 checklist included here?	Yes	Refer to attached checklist file



Annotated floor plan (2nd floor shown)



East elevation from original structural drawings



South elevation from original structural drawings




East elevation



West elevation



Roof greenhouses



UC Campus:	Santa Cruz		Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:	By Firm:	Maffei		
Building Name:	Thimann Laboratory		Initials:		Checked:	
Building Address:	568 Steinhart Way		Page:	1	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

LOW SEISMICITY

BUILDING SYSTEMS - GENERAL

	Description
C NC N/A U <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	LOAD PATH: The structure contains a complete, well-defined load path, including structural elements and connections, that serves to transfer the inertial forces associated with the mass of all elements of the building to the foundation. (Commentary: Sec. A.2.1.1. Tier 2: Sec. 5.4.1.1) Comments:
C NC N/A U <input type="radio"/> <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/>	ADJACENT BUILDINGS: The clear distance between the building being evaluated and any adjacent building is greater than 0.25% of the height of the shorter building in low seismicity, 0.5% in moderate seismicity, and 1.5% in high seismicity. (Commentary: Sec. A.2.1.2. Tier 2: Sec. 5.4.1.2) Comments: <i>Bridge to Sinseimer appears closely abutting from Google Satellite- no drawings reviewed.</i>
C NC N/A U <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	MEZZANINES: Interior mezzanine levels are braced independently from the main structure or are anchored to the seismic-force-resisting elements of the main structure. (Commentary: Sec. A.2.1.3. Tier 2: Sec. 5.4.1.3) Comments:

BUILDING SYSTEMS - BUILDING CONFIGURATION

	Description
C NC N/A U <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	WEAK STORY: The sum of the shear strengths of the seismic-force-resisting system in any story in each direction is not less than 80% of the strength in the adjacent story above. (Commentary: Sec. A.2.2.2. Tier 2: Sec. 5.4.2.1) Comments:
C NC N/A U <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/>	SOFT STORY: The stiffness of the seismic-force-resisting system in any story is not less than 70% of the seismic-force-resisting system stiffness in an adjacent story above or less than 80% of the average seismic-force-resisting system stiffness of the three stories above. (Commentary: Sec. A.2.2.3. Tier 2: Sec. 5.4.2.2) Comments:
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	VERTICAL IRREGULARITIES: All vertical elements in the seismic-force-resisting system are continuous to the foundation. (Commentary: Sec. A.2.2.4. Tier 2: Sec. 5.4.2.3) Comments: <i>If thin precast-prestressed wall panels were considered as part of the seismic force resisting, then the panels at the second level are not continuous to foundation. Panels are connected to columns only at floors.</i>

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	Santa Cruz		Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:	By Firm:	Maffei		
Building Name:	Thimann Laboratory		Initials:		Checked:	
Building Address:	568 Steinhart Way		Page:	2	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	GEOMETRY: There are no changes in the net horizontal dimension of the seismic-force-resisting system of more than 30% in a story relative to adjacent stories, excluding one-story penthouses and mezzanines. (Commentary: Sec. A.2.2.5. Tier 2: Sec. 5.4.2.4)
	Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	MASS: There is no change in effective mass of more than 50% from one story to the next. Light roofs, penthouses, and mezzanines need not be considered. (Commentary: Sec. A.2.2.6. Tier 2: Sec. 5.4.2.5)
	Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	TORSION: The estimated distance between the story center of mass and the story center of rigidity is less than 20% of the building width in either plan dimension. (Commentary: Sec. A.2.2.7. Tier 2: Sec. 5.4.2.6)
	Comments:

MODERATE SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW SEISMICITY)

GEOLOGIC SITE HAZARD

	Description
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance do not exist in the foundation soils at depths within 50 ft (15.2m) under the building. (Commentary: Sec. A.6.1.1. Tier 2: 5.4.3.1)
	Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	SLOPE FAILURE: The building site is located away from potential earthquake-induced slope failures or rockfalls so that it is unaffected by such failures or is capable of accommodating any predicted movements without failure. (Commentary: Sec. A.6.1.2. Tier 2: 5.4.3.1)
	Comments:
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site are not anticipated. (Commentary: Sec. A.6.1.3. Tier 2: 5.4.3.1)
	Comments:

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

If thin precast-prestressed wall panels were considered as part of the seismic force resisting, then there is torsion in the east-west direction, based on position of cast-in-place concrete shear walls.

UC Campus:	Santa Cruz		Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:	By Firm:	Maffei		
Building Name:	Thimann Laboratory		Initials:		Checked:	
Building Address:	568 Steinhart Way		Page:	3	of	3

ASCE 41-17 Collapse Prevention Basic Configuration Checklist

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR MODERATE SEISMICITY)

FOUNDATION CONFIGURATION

	Description
C NC N/A U <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/>	OVERTURNING: The ratio of the least horizontal dimension of the seismic-force-resisting system at the foundation level to the building height (base/height) is greater than $0.6S_a$. (Commentary: Sec. A.6.2.1. Tier 2: Sec. 5.4.3.3) Comments: <i>14'-4" long by 39 foot high walls do not meet test for $S_a = 1.5$. Wall foundations are not substantial.</i>
C NC N/A U <input type="radio"/> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/>	TIES BETWEEN FOUNDATION ELEMENTS: The foundation has ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Site Class A, B, or C. (Commentary: Sec. A.6.2.2. Tier 2: Sec. 5.4.3.4) Comments:

Note: C = Compliant NC = Noncompliant N/A = Not Applicable U = Unknown

UC Campus:	Santa Cruz		Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:	By Firm:	Maffei		
Building Name:	Thimann Laboratory		Initials:		Checked:	
Building Address:	568 Steinhart Way		Page:	1	of	3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2

LOW AND MODERATE SEISMICITY						
SEISMIC-FORCE-RESISTING SYSTEM						
		Description				
C	NC	N/A	U	COMPLETE FRAMES: Steel or concrete frames classified as secondary components form a complete vertical-load-carrying system. (Commentary: Sec. A.3.1.6.1. Tier 2: Sec. 5.5.2.5.1)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <i>Cast-in-place concrete walls at stair cores, which resist lateral seismic forces, are used to support gravity loads.</i>		
C	NC	N/A	U	REDUNDANCY: The number of lines of shear walls in each principal direction is greater than or equal to 2. (Commentary: Sec. A.3.2.1.1. Tier 2: Sec. 5.5.1.1)		
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments:		
C	NC	N/A	U	SHEAR STRESS CHECK: The shear stress in the concrete shear walls, calculated using the Quick Check procedure of Section 4.4.3.3, is less than the greater of 100 b/in.^2 (0.69 MPa) or $2\sqrt{f_c}$. (Commentary: Sec. A.3.2.2.1. Tier 2: Sec. 5.5.3.1.1)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <i>Walls are overstressed by factor of 1.4 at third level and 2.6 at first level</i>		
C	NC	N/A	U	REINFORCING STEEL: The ratio of reinforcing steel area to gross concrete area is not less than 0.0012 in the vertical direction and 0.0020 in the horizontal direction. (Commentary: Sec. A.3.2.2.2. Tier 2: Sec. 5.5.3.1.3)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <i>8 inch thick walls with #4 at 10" centers each way are .0016.</i>		
DIAPHRAGMS						
		Description				
C	NC	N/A	U	TOPPING SLAB: Precast concrete diaphragm elements are interconnected by a continuous reinforced concrete topping slab with a minimum thickness of 2 in. (51 mm). (Commentary: Sec. A.4.5.1. Tier 2: Sec. 5.6.4)		
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:		
CONNECTIONS						
		Description				
C	NC	N/A	U	TRANSFER TO SHEAR WALLS: Diaphragms are connected for transfer of seismic forces to the shear walls. (Commentary: Sec. A.5.2.1. Tier 2: Sec. 5.7.2)		
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <i>No substantial connection to wall between stair and elevator #2</i>		

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	Santa Cruz	Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:		By Firm:	Maffei
Building Name:	Thimann Laboratory	Initials:		Checked:	
Building Address:	568 Steinhart Way	Page:	2	of	3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2

C <input type="radio"/> NC <input type="radio"/> N/A <input checked="" type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>TOPPING SLAB TO WALLS OR FRAMES: Reinforced concrete topping slabs that interconnect the precast concrete diaphragm elements are doweled for transfer of forces into the shear wall or frame elements. (Commentary: Sec. A.5.2.3. Tier 2: Sec. 5.7.2)</p> <p>Comments:</p>
C <input type="radio"/> NC <input checked="" type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>FOUNDATION DOWELS: Wall reinforcement is doweled into the foundation. (Commentary: Sec. A.5.3.5. Tier 2: Sec. 5.7.3.4)</p> <p>Comments:</p>
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>GIRDER-COLUMN CONNECTION: There is a positive connection using plates, connection hardware, or straps between the girder and the column support. (Commentary: Sec. A.5.4.1. Tier 2: Sec. 5.7.4.1)</p> <p>Comments: <i>The connection is from the 13" thick floor slab to precast columns at perimeter. Connection has a small steel ledger for transfer of gravity load and a substantial embed dowel with plate washer connected to tendon into floor to tie column to floor..</i></p>

HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW AND MODERATE SEISMICITY)

SEISMIC-FORCE-RESISTING SYSTEM

				Description
C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input checked="" type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>PRECAST FRAMES: For buildings with concrete shear walls, precast concrete frame elements are not considered as primary components for resisting seismic forces. (Commentary: Sec. A.3.1.5.2. Tier 2: Secs. 5.5.2.4, 5.5.2.5.1, and 5.5.2.5.2)</p> <p>Comments: <i>Reviewer cannot clearly discern intended SLFRS for this building and considers the cast-in-place concrete shear walls as the only reliable vertical elements of the SLFRS.</i></p>
C <input checked="" type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>PRECAST CONNECTIONS: For buildings with concrete shear walls, the connection between precast frame elements, such as chords, ties, and collectors in the seismic-force-resisting system, develops the capacity of the connected members. (Commentary: Sec. A.3.1.5.3. Tier 2: Sec. 5.6.1.1)</p> <p>Comments: <i>Connections of precast columns to floors generally appear adequate to maintain connection</i></p>
C <input type="radio"/> NC <input checked="" type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>DEFLECTION COMPATIBILITY: Secondary components have the shear capacity to develop the flexural strength of the components. (Commentary: Sec. A.3.1.6.2. Tier 2: Sec. 5.5.2.5.2)</p> <p>Comments: <i>Reviewer could not locate a detail for the 2'-0" square reinforced concrete columns at the interior. Based on footing detail J-S9, columns have (16) and there are some light ties at wide spacing.</i></p>
C <input type="radio"/> NC <input type="radio"/> N/A <input checked="" type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	C <input type="radio"/> NC <input type="radio"/> N/A <input type="radio"/> U <input type="radio"/>	<p>COUPLING BEAMS: The ends of both walls to which the coupling beam is attached are supported at each end to resist vertical loads caused by overturning. (Commentary: Sec. A.3.2.2.3. Tier 2: Sec. 5.5.3.2.1)</p> <p>Comments:</p>

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	Santa Cruz	Date:	12/27/2018		
Building CAAN:	7116	Auxiliary CAAN:		By Firm:	Maffei
Building Name:	Thimann Laboratory		Initials:		Checked:
Building Address:	568 Steinhart Way		Page:	3	of 3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2

DIAPHRAGMS					
		Description			
C	NC	N/A	U	OPENINGS AT SHEAR WALLS: Diaphragm openings immediately adjacent to the shear walls are less than 25% of the wall length. (Commentary: Sec. A.4.1.4. Tier 2: Sec. 5.5.3.3.1)	
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <i>Wall between stair and elevator core not engaged to diaphragm.</i>	
CONNECTIONS					
		Description			
C	NC	N/A	U	UPLIFT AT PILE CAPS: Pile caps have top reinforcement, and piles are anchored to the pile caps. (Commentary: Sec. A.5.3.8. Tier 2: Sec. 5.7.3.5)	
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:	
C	NC	N/A	U	CORBEL BEARING: If the frame girders bear on column corbels, the length of bearing is greater than 3 in. (76 mm) (Commentary: Sec. A.5.4.3. Tier 2: Sec. 5.7.4.3)	
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:	
C	NC	N/A	U	CORBEL CONNECTIONS: The frame girders are not connected to corbels with welded elements. (Commentary: Sec. A.5.4.4. Tier 2: Sec. 5.7.4.3)	
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:	

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UC Santa Cruz			Date:	12/30/19		
Building CAAN:	7116	Auxiliary CAAN:		By Firm:	Maffei Structural Engineering		
Building Name:	Thimann Labs			Initials:	NY	Checked:	
Building Address:	568 Steinhart Way, CA 95064			Page:	1	of	3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2A

LOW AND MODERATE SEISMICITY							
SEISMIC-FORCE-RESISTING SYSTEM							
				Description			
C	NC	N/A	U	<p>REDUNDANCY: The number of lines of moment frames in each principal direction is greater than or equal to 2. The number of bays of moment frames in each line is greater than or equal to 2. (Commentary: Sec. A.3.1.1.1. Tier 2: Sec. 5.5.1.1)</p> <p>Comments:</p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>COLUMN SHEAR STRESS CHECK: The shear stress in the concrete columns, calculated using the Quick Check procedure of Section 4.4.3.2, is less than the greater of 100 lb/in.² (0.69 MPa) or $2 f_c$. (Commentary: Sec. A.3.1.4.1. Tier 2: Sec. 5.5.2.3.4)</p> <p>Comments: At Level 3, $V_{avg} = 147 \text{ psi} > 2 * \sqrt{5000} * 0.75 = 106.1 \text{ psi}$. At Level 1, $V_{avg} = 271 \text{ psi} > 106.1 \text{ psi}$.</p>			
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>COLUMN AXIAL STRESS CHECK: The axial stress caused by gravity loads in columns subjected to overturning forces is less than $0.10 f_c$. Alternatively, the axial stress caused by overturning forces alone, calculated using the Quick Check procedure of Section 4.4.3.6, is less than $0.30 f_c$. (Commentary: Sec. A.3.1.4.2. Tier 2: Sec. 5.5.2.1.3)</p> <p>Comments:</p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>PRECAST CONNECTION CHECK: The precast connections at frame joints have the capacity to resist the shear and moment demands calculated using the Quick Check procedure of Section 4.4.3.5. (Commentary: Sec. A.3.1.5.1. Tier 2: Sec. 5.5.2.4)</p> <p>Comments: Some frame action may have been assumed in the design through the couple between the connection to the 3rd and 2nd floors. Because the strength of the columns governed the building behavior, we did not check the capacity of the precast connections in moment.</p>			
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>				
DIAPHRAGMS							
				Description			
C	NC	N/A	U	<p>TOPPING SLAB: Precast concrete diaphragm elements are interconnected by a continuous reinforced concrete topping slab with a minimum thickness of 2 in. (51 mm). (Commentary: Sec. A.4.5.1. Tier 2: Sec. 5.6.4)</p> <p>Comments: No topping slab occurs, but floor diaphragm consists of continuous post-tensioned concrete slab.</p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UC Santa Cruz			Date:	12/30/19		
Building CAAN:	7116	Auxiliary CAAN:		By Firm:	Maffei Structural Engineering		
Building Name:	Thimann Labs			Initials:	NY	Checked:	
Building Address:	568 Steinhart Way, CA 95064			Page:	2	of	3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2A

CONNECTIONS							
				Description			
C	NC	N/A	U	<p>TOPPING SLAB TO WALLS OR FRAMES: Reinforced concrete topping slabs that interconnect the precast concrete diaphragm elements are doweled for transfer of forces into the shear wall or frame elements, and the dowels are able to develop the least of the shear strength of the walls, frames, or slabs. (Commentary: Sec. A.5.2.3. Tier 2: Sec. 5.7.2)</p> <p>Comments: <i>No topping slab occurs, but floor diaphragm consists of continuous post-tensioned concrete slab. Dowels from the slab to the shear wall or frame elements cannot develop the shear strength of the walls or frames.</i></p>			
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>GIRDER-COLUMN CONNECTION: There is a positive connection using plates, connection hardware, or straps between the girder and the column support. (Commentary: Sec. A.5.4.1. Tier 2: Sec. 5.7.4.1)</p> <p>Comments:</p>			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>				
HIGH SEISMICITY (COMPLETE THE FOLLOWING ITEMS IN ADDITION TO THE ITEMS FOR LOW AND MODERATE SEISMICITY)							
SEISMIC-FORCE-RESISTING SYSTEM							
				Description			
C	NC	N/A	U	<p>PRESTRESSED FRAME ELEMENTS: The seismic-force-resisting frames do not include any prestressed or post-tensioned elements where the average prestress exceeds the lesser of 700 lb/in.² (4.83 MPa) or $f'_c/6$ at potential hinge locations. The average prestress is calculated in accordance with the Quick Check procedure of Section 4.4.3.8. (Commentary: Sec. A.3.1.4.4. Tier 2: Sec. 5.5.2.3.2)</p> <p>Comments:</p>			
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>				
C	NC	N/A	U	<p>CAPTIVE COLUMNS: There are no columns at a level with height/depth ratios less than 50% of the nominal height/depth ratio of the typical columns at that level. (Commentary: Sec. A.3.1.4.5. Tier 2: Sec. 5.5.2.3.3)</p> <p>Comments:</p>			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>JOINT REINFORCING: Beam-column joints have ties spaced at or less than $8d_b$. (Commentary: Sec. A.3.1.4.13. Tier 2: Sec. 5.5.2.3.8)</p> <p>Comments: <i>Precast columns have ties spaces at 14" = 16db for #7 vertical column reinforcement.</i></p>			
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>				
C	NC	N/A	U	<p>DEFLECTION COMPATIBILITY: Secondary components have the shear capacity to develop the flexural strength of the components. (Commentary: Sec. A.3.1.6.2. Tier 2: Sec. 5.5.2.5.2)</p> <p>Comments: <i>We could not find details of the interior concrete columns other than a detail of the connection to the footing (J-S9). Based on this and other details, we expect that the columns are lightly tied and prone to shear failure.</i></p>			
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>				

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown

UC Campus:	UC Santa Cruz			Date:	12/30/19		
Building CAAN:	7116	Auxiliary CAAN:		By Firm:	Maffei Structural Engineering		
Building Name:	Thimann Labs			Initials:	NY	Checked:	
Building Address:	568 Steinhart Way, CA 95064			Page:	3	of	3

ASCE 41-17 Collapse Prevention Structural Checklist For Building Type PC2A

CONNECTIONS							
				Description			
C	NC	N/A	U	UPLIFT AT PILE CAPS: Pile caps have top reinforcement, and piles are anchored to the pile caps. (Commentary: Sec. A.5.3.8. Tier 2: Sec. 5.7.3.5)			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:			
C	NC	N/A	U	GIRDERS: Girders supported by walls or pilasters have at least two ties securing the anchor bolts unless provided with independent stiff wall anchors with strength to resist the connection force calculated in the Quick Check procedure of Section 4.4.3.7. (Commentary: Sec. A.5.4.2. Tier 2: Sec. 5.7.4.1)			
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments:			
C	NC	N/A	U	CORBEL BEARING: If the frame girders bear on column corbels, the length of bearing is greater than 3 in. (76 mm) (Commentary: Sec. A.5.4.3. Tier 2: Sec. 5.7.4.3)			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:			
C	NC	N/A	U	CORBEL CONNECTIONS: The frame girders are not connected to corbels with welded elements. (Commentary: Sec. A.5.4.4. Tier 2: Sec. 5.7.4.3)			
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	Comments:			

Note: **C** = Compliant **NC** = Noncompliant **N/A** = Not Applicable **U** = Unknown



Project: _____

Subject: _____

By: _____

Date: _____

SEISMIC EVALUATION OF EXISTING BUILDINGS - TIER 1 SCREENING

ASCE 41-17 Chapter 4

General

Architect	Anshen & Allen		
Structural Engineer	TY Lin and Assoc		
Location	568 Steinhart Way, Santa Cruz, CA 95064		
Design date	1964		
Latitude	36.998097		
Longitude	-122.061995		
Stories above grade	3	plus rooftop structures	

Reference

<https://hazards.atcouncil.org/>

"

Seismic parameters

Risk Category	II	2016 CBC Table 1604.5	
Site Class	D	Assumed	(ASCE 41-17 2.4.1.6, ASCE 7-16 Chapter 20)
Liquefaction hazard	Low	Assumed	(ASCE 41-17 3.3.4)
Landslide hazard	Low	Assumed	
S_{DS}	1.306	https://hazards.atcouncil.org/	Based on ASCE 7-16 DE, used to determine "Level of Seismicity" (ASCE 41-17 Eq 2-4)
S_{D1}	0.585	https://hazards.atcouncil.org/	Based on ASCE 7-16 DE, used to determine "Level of Seismicity" (ASCE 41-17 Eq 2-5)
S_{XS}	1.286	For BSE-2E hazard level	https://hazards.atcouncil.org/ (ASCE 41-17 Table 2-2)
S_{X1}	0.89	For BSE-2E hazard level	https://hazards.atcouncil.org/ (ASCE 41-17 Table 2-2)

Scope

Performance level	Collapse Prevention	Ms = 2	(ASCE 41-17 Sec 4.4.3.2)	(ASCE 41-17 Table 2-2)
Seismic hazard level	BSE-2E			(ASCE 41-17 Table 2-2)
Level of seismicity	High			(ASCE 41-17 Table 2-4)
Building type	PC2a - Precast Concrete Frame without Shear Walls			(ASCE 41-17 Table 3-1)

Material properties

			Notes		
Concrete	f'_c	5,000 Lwt	psi	Precast Columns	(ASCE 41-17 Table 10-4)
		4,000 Lwt		Floors	
		5,000 Lwt		P/C walls	
Reinf.	f_y	40	ksi	Typical	(ASCE 41-17 Table 10-4)
		60		Column Verticals	
Steel	F_y	N/A	ksi	N/A	(ASCE 41-17 Table 9-1)



www.maffei-structure.com

Project: _____
 Subject: _____
 By: _____
 Date: _____

Checklists

Benchmark building	No	(ASCE 41-17 Table 3-2)
Checklist(s) req'd	17.1.2 Basic Configuration	(ASCE 41-17 Table 4-6)
	17.12 Structural Checklist for Building Types PC2a	(ASCE 41-17 Table 4-6)
	17.19 Nonstructural Checklist (not performed)	(ASCE 41-17 Table 4-6)

Seismic forces

V	16718	kip	$V = C_s a W$	= 1.29W	(ASCE 41-17 Eq 4-1)
W	13000	kip	building weight		(ASCE 41-17 4.4.2.1)
C	1.0		Convert linear elastic to inelastic disp.		(ASCE 41-17 Table 4-7)
S_a	1.29	g	$S_a = S_{x1}/T \leq S_{x5}$		(ASCE 41-17 Eq 4-3)
T	0.32	sec	$T = C_t h_n^\beta$		(ASCE 41-17 Eq 4-4)
C_t	0.020				(ASCE 41-17 Eq 4-4)
β	0.75				(ASCE 41-17 Eq 4-4)
h_n	41	ft	building height		(ASCE 41-17 Eq 4-4)

Story Forces

(ASCE 41-17 4-2a) (ASCE 41-17 4-2b)

Story	w kip	story ht ft	h ft	wh^k	F_{story}	F_{story} kip	V_{story} kip
Roof	5000		41	202500	0.56	9288	
3	4000	13.5	27	108000	0.30	4953	9288
2	4000	13.5	14	54000	0.15	2477	14241
1		13.5	0				16718
Total	13000			364500	1.0	16718	

k 1.00 $k = 1.0$ for $T < 0.5$, 2.0 for $T > 2.5$, linear interpolation between

$F_{story} = V(wh^k)/(\sum wh^k)$ (ASCE 41-17 4-2a)

$V_{story} = \sum_{above} F_{story}$ (ASCE 41-17 4-2b)

Shear stress in precast columns (ASCE 41-17 4-7)

Story	n_c	n_f	A_c in ²	v^{avg} psi	D/C	
Roof						
3	68	2	32544	147	1.4	Includes 68 column plus 3168 in ² for 8" wall
2 N/S			24672	289	2.7	Includes 7680 in ² 4" wall + 3168 in ² 8" wall + 48 col * 2* 6" x 24" columns at N and S walls
2 E/W			22240	320	3.0	Includes 17280 in ² 4" wall + 4960 in ² 8" wall
1	68	2	31824	271	2.6	Includes 68 columns plus 3168 in ² for 8" wall
Total						

M_s 2.00 (ASCE 41-17 Table 4-8)

v_{limit} 106 psi $v_{limit} = 2v_{f_c}' \geq 100$ psi

$v^{avg} = (1/M_s)(n_c/(n_c-n_f))(V_{story}/A_c)$ (ASCE 41-17 Eq 4-8)

When no columns, $v^{avg} = (1/MS)(V_{story}/A_c)$

Weight takeoff

	Floor	Roof
Floor Slab	120 psf	120 psf
Rooftop		40 psf
Partitions	10	5
Ceiling, Mech	12	12
Exterior cladding	15	30
Columns	10 psf	5 psf
Total	167 psf	212 psf
Weight	3925 kps	4982 kps